

5

METHOD FOR COATING PARTICLES

10

ABSTRACT OF THE DISCLOSURE

15 A method for coating inorganic particles with a metal compound is performed by the steps of: preparing a dispersion which comprises a metal salt and inorganic particles in a molten organic material which takes a solid form at 25°C, is converted into a polar liquid by heating and decomposes by further heating; and heating the dispersion, whereby coating the inorganic particles with a metal compound which is converted from the metal salt.